

PORTACOUNT[®] PRO 8030 AND PORTACOUNT[®] PRO+ 8038 RESPIRATOR FIT TESTERS

FIRMWARE UPDATE INSTRUCTIONS

Firmware Update Instructions Version 2.5

The PORTACOUNT[®] PRO Firmware Update application loads firmware to a TSI[®] PORTACOUNT[®] PRO instrument through a USB connection. The PORTACOUNT[®] PRO Firmware Update runs on a computer with Microsoft Windows[®] XP or Vista[®] (32-bit only), or Windows[®] 7 (32-bit or 64-bit) operating system. This application is to be used with TSI PORTACOUNT[®] PRO instruments only.

This document contains three parts: a [Quick Installation Guide](#), a [Detailed Installation Guide](#), and a [USB Firmware Upload Guide](#). These guides describe how to access programs from the TSI website or CD needed for installing (uploading) new firmware to your PORTACOUNT[®] PRO instrument. These guides also describe how to upload the new firmware to your PORTACOUNT[®] PRO instrument. If needed, the [Detailed Installation Guide](#) and [USB Firmware Update Guide](#) sections provide additional information useful when uploading the firmware from your computer to the PORTACOUNT[®] PRO instrument.

Quick Installation Guide

This quick installation guide describes the process of obtaining the latest PORTACOUNT[®] PRO firmware and uploading this firmware to your PORTACOUNT[®] PRO Respirator Fit Tester. The best method of accessing updates to your PORTACOUNT[®] PRO Operation Firmware is from the TSI website. In this way you are assured of getting the latest firmware version. If you are unable to successfully download the firmware from the TSI website, please contact TSI support.

Obtaining the Latest PORTACOUNT[®] PRO Firmware and Update Program from the TSI Website

1. From your computer, access the TSI web page <http://www.tsi.com/SoftwareDownloads> and follow the instructions on the web page to locate firmware for your PORTACOUNT[®] Respirator Fit Tester.
2. Click on the resulting Firmware Update link to download the file to your computer.

TSI and PORTACOUNT PRO are registered trademarks of TSI Incorporated.
Microsoft and Windows are registered trademarks of Microsoft Corporation.



3. Once the download is complete, double-click on the downloaded file. This installs the PORTACOUNT[®] PRO Firmware Upload program needed to upload the new firmware to your PORTACOUNT[®] PRO instrument.
4. Complete the installation process by selecting **Next**, **Next**, **Install**, and **Finish** buttons as required.
5. Proceed to “[Uploading the Latest Firmware to your PORTACOUNT[®] PRO Respirator Fit Tester](#)” to upload the new firmware to your PORTACOUNT[®] PRO fit tester.

Uploading the Latest Firmware to your PORTACOUNT[®] PRO Respirator Fit Tester

1. Once the firmware upload application programs are on your computer (see previous sections), the firmware can be transferred to your PORTACOUNT[®] PRO fit tester.
2. Using a USB cable, connect to the Series B receptacle (square shape) on your PORTACOUNT[®] PRO fit tester and to a USB receptacle on your computer.
3. Turn on the PORTACOUNT[®] PRO fit tester and allow it to complete its initialization sequence. If the New Hardware Wizard appears, simply follow the prompts to install the TSI NDIS driver. Continue past any warnings and press **Finish**.
4. Find the new TSI Update PORTACOUNT[®] Firmware icon on your computer’s Desktop. This runs the Update program. Click on the icon to start the application.
5. Click the green button in the upper left corner of the first program screen. The PORTACOUNT[®] PRO fit tester display and pump will turn off during this part of the update process.
6. If this is the first time the PORTACOUNT[®] PRO firmware has been updated, another New Hardware Wizard will appear. Simply follow the prompts to install the TSI USB driver. Continue past any warnings and press **Finish**. If the firmware update program “times out” during the TSI USB driver install, click the green button in the upper left corner again.
7. Once started, the firmware update process should take approximately 10 minutes. During this time, observe the warnings regarding interrupting the program upload.
8. After the update is completed successfully, power down your PORTACOUNT[®] PRO Respirator Fit Tester. Wait 10 seconds and power up the instrument.
9. On the PORTACOUNT[®] PRO screen, go to the **Setup tab** and select **Device Info**.
10. Verify the Build String is the version of the firmware update, e.g., 2.5.

A “Detailed Installation Guide” is presented in the section which follows. Refer to this section if you had difficulty installing the firmware using the simplified Quick Installation Guide, or if errors were encountered.

Detailed Installation Guide

Installation Instructions

1. After installation from the TSI website, as described in the Quick Installation Guide, run **TSI_PortaCount_Firmware_Update_Utility_v2.5.exe**. If you are using the Firmware Update CD, select the menu item **Install PortaCount Pro Firmware Update Utility**.
2. A “Preparing to Install...” screen will be displayed.




Figure 1

3. Select the **Next >** button to continue the installation (**Error! Reference source not found.**).




Figure 2

4. Install to the default location by selecting the **Next >** button or change the location of the installed files by selection the **Change...** button (Figure 3).




Figure 3

5. Select the **Install** button to continue the installation (Figure 4).




Figure 4

6. Wait for the installation to finish.




Figure 5

7. Select the **Finish** button to complete the installation (Figure 6).




Figure 6

8. Attach the powered instrument to the system. If the instrument has not been attached to the system previously, the Found New Hardware Wizard *may* be displayed (see steps 9 to 14). Once this step is complete an Icon is placed on your Desktop. This is used to upload the firmware to your instrument as described in the section [USB Firmware Upload Instructions](#).
9. Select **No, not this time** to not search the Windows[®] Update website. Then select the **Next >** button (**Error! Reference source not found.**).




Figure 7

10. Select the **Install the software automatically** action then, select the **Next >** button (**Error! Reference source not found.**).




Figure 8

11. Select the **Continue Anyway** button (**Error! Reference source not found.**).



Figure 9

12. Make sure that the device installed without any errors. Select **Finish** to complete the device installation and exit the dialog (Figure 16).



Figure 10

The PORTACOUNT[®] PRO instrument is installed on the system and ready to run with the Firmware Upload application.

USB Firmware Upload Guide

This installation requires a Windows® XP or Vista® (32-bit only), or Windows® 7 (32 or 64 bit) operating system. For best results run the USB Firmware Upload application with a single TSI PORTACOUNT® PRO instrument attached to your system.

To upload firmware to the instrument, click on the new PORTACOUNT® Firmware Update Utility icon on your computer's desktop to run the USB firmware update application. The following screen appears.





Figure 11

1. Connect your PORTACOUNT® PRO instrument to the computer using a USB cable. Turn the PORTACOUNT® PRO instrument power ON. Wait for approximately one minute for the instrument to connect and become active on the system.
2. Click the green **START**  button to start the firmware update process.

In the event that the instrument is not attached or not powered, the following error will be shown in the status box of the application (**Error! Reference source not found.**):

"ERROR: An instrument is not attached"




Figure 12

3. The PORTACOUNT[®] PRO instrument requires a switch in operation modes to allow firmware uploading to occur. Once the mode switch occurs, the Found New Hardware Wizard may be shown (steps 4 through 7).

Allow the installation of the device on the system by following the Found New Hardware Wizard (**Error! Reference source not found.** through 16).

4. Select **No, not this time** to not search the Windows Update website. Then select the **Next >** button (**Error! Reference source not found.**).




Figure 13

5. Select **Install the software automatically**, the recommended action. Then select the **Next >** button (**Error! Reference source not found.**).




Figure 14

6. Select the **Continue Anyway** button (**Error! Reference source not found.**).




Figure 15

7. Make sure that the device installed without any errors. Select **Finish** to complete the device installation and exit the dialog (Figure 16).



Figure 16

8. If the Firmware Upload application is displaying an error message similar to Figure 12, restart the Firmware Upload process by clicking the green **START**  button.

9. In the event of the following message shown in the status box of the application:

"ERROR: The Instrument Model is not supported. Please download the correct firmware upload application for the <XXX> instrument model"

Make sure that the firmware upgrade you have is correct for the model of your instrument. The model of your instrument is displayed in the <XXX> placeholder of the message. If the problem persists, contact TSI customer service at 1-800-874-2811 or email technical.service@tsi.com to receive the correct firmware upgrade configuration for your instrument.

10. If the application detects that the firmware that is installed on the attached instrument is the same firmware that is being installed, a message will be displayed (Figure 17).

Select **Yes** to rewrite or repair the existing firmware on the instrument. Select **No** if you do not need to rewrite the firmware on the instrument.




Figure 17

Selecting **Yes** will continue the installation.

11. The process of uploading firmware to an instrument will go through a series of erasing and writing firmware images. The number of images depends on the instrument and the released firmware. The status box of the application will list the firmware uploading tasks as completed. The progress bar of the application will update as the firmware images are written to the device.




Figure 18

12. When the firmware upload process is complete, the success message is displayed (Figure 19).




Figure 19

13. The software will prompt the user to exit at this point (**Error! Reference source not found.**).





Figure 20

14. After the update is completed successfully, power down your PORTACOUNT[®] PRO Respirator Fit Tester. Wait 10 seconds and power up the instrument.

15. On the PORTACOUNT[®] PRO screen, go to the **Setup tab** and select **Device Info**.

16. Verify the Build String is the version of the firmware update, e.g. 2.5.

The STOP Button

When the **Stop**  button is clicked, the following message appears:

"It is not recommended to select the Stop button during a firmware download".

Since it is necessary to erase the existing firmware of the instrument to write the new firmware of the device, the instrument will maintain an inoperable state until a complete and successful firmware upload occurs.

The following warning is displayed when the **Stop**  button is pressed (**Error! Reference source not found.**).




Figure 21

If the **No** button is clicked, the firmware upload will continue to upgrade the firmware of the instrument.

If the **Yes** button is clicked, the Firmware upgrade process will halt.

The following messages are displayed.

CANCELLED: The firmware update process has been cancelled.

This may result in an inoperable instrument!

Please power down the instrument for at least five seconds then power on the instrument for at least 60 seconds prior to restarting any subsequent firmware updates.

Please update the firmware prior to using the instrument.




Figure 22

Instrument Connection

If the instrument connection is disrupted or any error occurs during the firmware upgrade process, an error is reported. It is recommended to:

1. Power down the instrument.
2. Check the instrument cables.
3. Restart the firmware upgrade.

If the problem persists, please contact TSI customer service at www.TSI.com, 1-800-874-2811 or email technical.service@tsi.com to resolve the issue.




Figure 23



UNDERSTANDING, ACCELERATED

TSI Incorporated – Visit our website www.tsi.com for more information.

USA	Tel: +1 800 874 2811	India	Tel: +91 80 67877200
UK	Tel: +44 149 4 459200	China	Tel: +86 10 8251 6588
France	Tel: +33 4 91 11 87 64	Singapore	Tel: +65 6595 6388
Germany	Tel: +49 241 523030		