## PortaCount<sup>™</sup> Respirator Fit Tester Network Connectivity Enhancement



For Model 8040 and 8048

Application Note RFT-031 (US)

A newly available software and firmware update for PortaCount<sup>™</sup> Respirator Fit Tester Models 8040 and 8048 now supports a second USB communication mode, **USB Serial.** This mode allows for greater versatility when integrating PortaCount<sup>™</sup> instruments and FitPro<sup>™</sup> Ultra software running on Windows<sup>®</sup> devices (laptops, desktops or tablets) in corporate networks. Corporate networks have seen increased security from Microsoft<sup>®</sup> Operating Systems and network administrators. USB Serial will now be the default communication mode. This enhancement requires both an update to the instrument's firmware and the FitPro<sup>™</sup> Ultra software on Windows<sup>®</sup> devices.

## Updating the Software and Firmware

Download software and firmware updates at: <u>https://tsi.com/software/tsi-software-and-firmware-wizard/</u>.

- 1. In the search box, type "PortaCount," select Model 8040 or 8048 and click "Search."
- 2. Download the PortaCount<sup>™</sup> Firmware Update v1.3.1.
  - a. Save the zip file and unzip it to obtain file "pc-804x-1.3.1.swu."
  - b. Save that file to a thumb-drive. Ensure this is the only firmware file on the thumb-drive, delete any other \*.swu files if present.
  - c. Download the Firmware Update Instructions and the new software "FitPro Ultra v4.9.0 Software Setup."
- 3. Alternately, new software can be obtained in FitPro<sup>™</sup> Ultra software itself when connected to the internet; FitPro<sup>™</sup> Ultra software will detect the availability of the v4.9 upgrade.
- 4. Installation:

www.tsi.com

- a. Install the FitPro<sup>™</sup> Ultra Software first.
- b. Then follow the Firmware Update Instructions to update the PortaCount firmware.
- 5. After installing the new software and firmware updates, reboot the PortaCount instrument and reconnect the computer.
- 6. Select PortaCount<sup>™</sup> Settings, and on this screen verify that the firmware is updated to version 1.3.1 and that the USB Connection Type has been set to VCOM (USB Serial).



You are now ready to use USB Serial connectivity mode. Some of the typical connection configuration examples are shown in the next page.

If you have any questions, please contact TSI<sup>®</sup> Incorporated's Customer/Technical Support at 800-680-1220 or <u>answers@tsi.com</u> / <u>technical.services@tsi.com</u>.

## **Configuration Examples**

With the new PortaCount<sup>™</sup> firmware v1.3.1 and FitPro<sup>™</sup> Ultra v4.9.0 software, the default connection type is USB Serial. Here are a few configuration examples showing best-practice connections when using a FitPro Ultra software

	GENERAL	NETWORK
PORTACOUNT NAME tsi-8048173604		
Device Informa	tion	
Model Number	: 8048	
Serial Number:	8048173604	
Firmware Versi	on: 1.3.1	
USB Connectio	n Type	
	twork)	

on a Windows<sup>®</sup> computer (desktop/laptop PC or Windows<sup>®</sup> operating system tablet) on a Local Area Network (LAN).





TSI and the TSI logo are registered trademarks of TSI Incorporated in the United States and may be protected under other country's trademark registrations.

Microsoft and Windows are registered trademarks of Microsoft Corporation.

Wi-Fi is a registered trademark of Wi-Fi Alliance.



TSI Incorporated – Visit our website www.tsi.com for more information.

 USA
 Tel: +1 800 680 1220
 India
 Tel: +91 80 67877200

 UK
 Tel: +44 149 4 459200
 China
 Tel: +86 10 8219 7688

 France
 Tel: +33 1 41 19 21 99
 Singapore Tel: +65 6595 6388

 Germany Tel: +49 241 523030
 Singapore Tel: +65 6595 6388

RFT-031 Rev C (US) (9/6/2023) ©2023 TSI Incorporated Printed in U.S.A.