

TSI® Model 4199 Flowmeter Battery Pack and Stand

Operation and Service Manual

1980504, Revision B
January 2009



This battery pack works with the TSI Series 4000 and 4100 Flowmeters that have LCD displays. Flowmeters manufactured before August 2004 will not indicate low battery. For those meters, the meter will work properly until the display locks up; replace batteries at that time.

List of Components

1 - Battery pack	2 - 4000 Series lugs
2 - 4100 Series lugs	6 - AA batteries

Installation

Screw in both lugs to back side of flowmeter (the front being the display). 4000 and 4100 series flowmeters require different size lugs. Line up lugs with the holes on top of the battery pack. Press one lug in at a time. Attach cable to flowmeter.

Removal

Unplug power cable and then rotate the bottom of the meter away from the battery pack until lugs disengage from battery pack.

TSI Incorporated – 500 Cardigan Road, Shoreview, MN 55126 U.S.A

USA	Tel: +1 800 874 2811	E-mail: info@tsi.com	Website: www.tsi.com
UK	Tel: +44 149 4 459200	E-mail: tsiuk@tsi.com	Website: www.tsilinc.co.uk
France	Tel: +33 491 95 21 90	E-mail: tsifrance@tsi.com	Website: www.tsilinc.fr
Germany	Tel: +49 241 523030	E-mail: tsigmbh@tsi.com	Website: www.tsilinc.de
India	Tel: +91 80 41132470	E-mail: tsi-india@tsi.com	
China	Tel: +86 10 8260 1595	E-mail: tsibeijing@tsi.com	



Contact your local TSI Distributor or visit our website www.tsi.com for more detailed specifications.