

Nanoparticle Surface Area Monitor*

Model 3550

Standard replacement parts for Model 3550 Nanoparticle Surface Area Monitor consist of:

<u>Part Number</u>	<u>Part Description</u>
1031579	3550/3070A Maintenance Kit: includes (2) 1602230; (1) 1602346; (1) 1602348;
1030536	(1) 1030319R
1602230	Cyclone 1 micron 3550 & 3070A
1602346	Filter (DFU-BX)
1602348	Filter Wire Core Microfiber
1030319R	Carbon Capsule DAU
	Charger Head Replacement

For pricing information, or to place an order you can 1) send the necessary information to answers@tsi.com or 2) contact your local TSI representative (see contact information below) and speak to one of our customer specialists. Please include your contact information (telephone number and mailing address) with all requests.

*U.S. Patents 6,544,484 and 7,812,306

TSI Incorporated – 500 Cardigan Road, Shoreview, MN 55126 U.S.A

USA	Tel: +1 800 874 2811	E-mail: particle@tsi.com	Website: www.tsi.com
UK	Tel: +44 149 4 459200	E-mail: tsiuk@tsi.com	Website: www.tsiinc.co.uk
France	Tel: +33 491 11 87 64	E-mail: tsifrance@tsi.com	Website: www.tsiinc.fr
Germany	Tel: +49 241 523030	E-mail: tsigmbh@tsi.com	Website: www.tsiinc.de
India	Tel: +91 80 41132470	E-mail: tsi-india@tsi.com	
China	Tel: +86 10 8251 6588	E-mail: tsibeijing@tsi.com	
Singapore	Tel: +65 6595 6388	E-mail: tsi-singapore@tsi.com	

Contact your local TSI Distributor or visit our website www.tsi.com for more detailed specifications.



TRUST. SCIENCE. INNOVATION.